| ef. | Part No. | Part Name & Description | Remarks |
|------------|----------------------------|-------------------------|---------|
| E | ERJ3GEYJ224 | 220k | |
| 5 | ERJ3GEYJ473 | 47k | |
| R36 | ERJ3GEYJ202 | 2k | |
| R37 | ERJ3GEYJ102 | 1k | |
| R38 | ERJ3GEY0R00 | 0 | |
| R39 | ERJ3GEYJ224 | 220k | |
| R40 | ERJ3GEYJ330 | 33 | |
| R41 | ERJ3GEYJ683 | 68k | |
| R42 | ERJ3GEYJ223 | 22k | |
| R43 | ERJ3GEYJ104 | 100k | |
| R44 | ERJ3GEYJ393 | 39k | |
| R45 | ERJ3GEYJ104 | 100k | |
| R46 | ERJ3GEYJ434 | 430k | |
| R47 | ERJ3GEYJ222 | 2.2k | |
| R48 | ERJ3GEYJ223 | 22k | |
| R49 | ERJ3GEYJ473 | 47k | |
| R50 | ERJ3GEYJ822 | 8.2k | |
| R51 | ERJ3GEYJ272 | 2.7k | |
| R52 | ERJ3GEYJ681 | 680 | |
| R53 | ERJ3GEYJ820 | 82 | |
| R54 | ERJ3GEYJ104 | 100k | |
| R55 | ERJ3GEYJ390 | 39 | |
| R56 | ERJ3GEYJ222 | 2.2k | |
| R57 | ERJ3GEYJ332 | 3.3k | |
| R58 | ERJ3GEYJ470 | 47 | |
| R59 | ERJ3GEYJ222 | 2.2k | |
| R60 | ERJ3GEYJ222 | 2.2k | |
| R61 | ERJ3GEYJ331 | 330 | |
| R62 | ERJ3GEYJ222 | 2.2k | |
| R63 | ERJ3GEYJ103 | 10k | |
| R64 | ERJ3GEYJ103 | 10k | |
| R65 | ERJ3GEYJ331 | 330 | |
| R66 | ERJ3GEYJ222 | 2.2k | |
| R67 | ERJ3GEYJ222 | 2.2k | |
| R68 | ERJ3GEYJ103 | 10k | |
| R69 | ERJ3GEYJ222 | 2.2k | |
| R70 | ERJ3GEYJ222 | 2.2k | |
| R72 | ERJ3GEYJ105 | 1M | |
| R74 | ERJ3GEYJ104 | 100k | |
| R75 | ERJ3GEYJ104 | 100k | |
| R76 | ERJ3GEYJ104 | 100k | |
| R77 | ERJ3GEYJ103 | 10k | |
| R78 | ERJ3GEYJ104 | 100k | |
| R79 | ERJ3GEYJ105 | 1M | |
| R81 | ERJ3GEYJ105 | 1M | |
| R82 | ERJ3GEY0R00 | 0 | |
| | _ | <u> </u> | |
| R83 R84 | ERJ3GEY0R00 | 0 1M | + |
| R84 R85 | ERJ3GEYJ105 | | + |
| | ERJ3GEYJ102 | 100- | + |
| R86 | ERJ3GEYJ104 | 100k | + |
| R87 | ERJ3GEYJ104 | 100k | + |
| R91 | ERJ3GEY0R00 | 0 | |
| R93 | ERJ3GEYJ103 | 10k | + |
| R94 | ERJ3GEYJ334 | 330k | + |
| R95 | ERJ3GEYJ393 | 39k | + |
| R96 | ERJ3GEY0R00 | 0 | + |
| R97 | ERJ3GEYJ104 | 100k | |
| R98 | ERJ3GEYJ475 | 4.7M | + |
| R99 | ERJ3GEYJ472 | 4.7k | |
| R101 | ERJ3GEY0R00 | 0 | |
| R103 | ERJ3GEYJ105 | 1M | |
| R105 | ERJ3GEYJ103 | 10k | |
| R106 | ERJ3GEYJ151 | 150 | |
| R107 | ERJ3GEYJ222 | 2.2k | |
| R108 | ERJ3GEYJ102 | 1k | |
| R109 | ERJ3GEYJ102 | 1k | |
| R110 | ERJ3GEYJ102 | 1k | |
| R111 | ERJ3GEYJ102 | 1k | |
| R112 | ERJ3GEYJ102 | 1k | |
| | | (CAPACITORS) | |
| | | | |
| C1 | ECEA1EK470 | 47 | s |
| | ECEA1EK470 ECUV1H473MDV | 0.047 | s s |

| | кх- | TC1205RUB / KX-TC1205RUW / KX-TC1205 | RU. POF-XCh |
|------------|------------------------------|--------------------------------------|--------------|
| Ref. | Part No. | Part Name & Description | harks |
| No. | ECUV1H270JCV | 27p | & Attoput |
| C5 | ECUV1C104ZFV | 0.1 | Mar Colo |
| C6 | ECUV1H102KBV | 0.001 | acker-so |
| C7 | ECUV1C104ZFV | 0.1 | • |
| C8 | ECUV1H473MDV | 0.047 | s |
| C9 | ECUV1H103KBV | 0.01 | |
| C12 C13 | ECEA1HKA2R2 ECUV1H270JCV | 2.2 27p | |
| C14 | ECUV1H103KBV | 0.01 | |
| C15 | ECEA1CKA100 | 10 | |
| C16 | ECUV1C473KBV | 0.047 | |
| C17 | ECUV1H102KBV | 0.001 | |
| C18 | ECEA1HKA2R2 | 2.2 | - |
| C21 | ECUV1H223KBV | 0.022 | S |
| C22 C23 | ECUV1H390JCV ECUV1H102KBV | 0.001 | |
| C24 | ECUV1H220JCV | 22p | |
| C26 | ECUV1H103KBV | 0.01 | |
| C27 | ECUV1C104KBV | 0.1 | |
| C28 | ECUV1H682KBV | 0.0068 | |
| C29 | ECEA1HKA2R2 | 2.2 | + |
| C30 | ECUV1C104KBV | 0.1 | |
| C31 | ECUV1H103KBV | 0.01 | + |
| C32 | ECUV1C104KBV ECUV1C104KBV | 0.1 | + |
| C34 | ECUV1H101JCV | 100p | + |
| C35 | ECUV1H681JCV | 680p | |
| C36 | ECUV1H180JCV | 18p | |
| C37 | ECEA1HKA010E | 1 | |
| C38 | ECUV1H101JCV | 100p | |
| C39 | ECUV1H151JCV | 150p | |
| C40 | ECUV1H103KBV | 0.01 | S |
| C41 C42 | ECUV1H220JCV ECEA1EK470 | 22p 47 | s |
| C42 | ECEA1HKA2R2 | 2.2 | |
| C44 | ECUV1C105ZFV | 1 | |
| C45 | ECUV1C683KBV | 0.068 | |
| C47 | ECUV1H682KBV | 0.0068 | |
| C48 | ECEA1EK470 | 47 | s |
| C49 | ECUV1H223KBV | 0.022 | s |
| C50 | ECUV1H103KBV | 0.01 | S |
| C51 C52 | ECEA1CKA100 ECUV1H103KBV | 0.01 | s |
| C52 | ECUV1H223KBV | 0.022 | s |
| C54 | ECUV1H100DCV | 10p | s |
| C55 | ECUV1H103KBV | 0.01 | s |
| C56 | ECUV1H010CCV | 1p | |
| C57 | ECUV1H150JCV | 15p | |
| C58 | ECUV1H103KBV | 0.01 | |
| C59 | ECUV1H270JCV | 27p | + |
| C60 C61 | ECUV1H270JCV ECUV1C104ZFV | 0.1 | + |
| C62 | ECUV1CIO42FV ECUV1H560JCV | 56p | + - |
| C63 | ECEA1CK101 | 100 | s |
| C64 | ECUV1H103KBV | 0.01 | s |
| C65 | ECUV1H150JCV | 15p | |
| C66 | ECUV1H150JCV | 15p | \perp |
| C69 | ECUV1C104ZFV | 0.1 | |
| C70 | ECUV1H330JCV | 33p | + |
| C71 C72 | ECUV1H330JCV ECUV1C104ZFV | 0.1 | + |
| C72 | ECUV1C104ZFV | 0.1 | + |
| C74 | ECUV1H473MDV | 0.047 | s |
| C75 | ECUV1H103KBV | 0.01 | |
| C76 | ECUV1H471JCV | 470p | |
| C77 | ECUV1H471JCV | 470p | |
| C78 | ECUV1H103KBV | 0.01 | |
| C79 | ECUV1H103KBV | 0.01 | |
| C80 | ECUV1H103KBV | 0.01 | |
| C84 | ECUV1C104ZFV | 0.1 | + |
| COF | | 14 | |
| C85 C86 | ECUV1C105ZFV ECUV1C104ZFV | 0.1 | + - |